

**TRIAD**  
Extreme UNIVERSAL



HEAT: 500 °C  
SPEED: 40%

**T3**  
Extreme



HEAT: 430 °C  
SPEED: 4

**T300**  
Extreme



Hot Air Welding  
HEAT: 500 °C  
SPEED: 6 M/MIN

Hot Wedge Welding  
HEAT: 430 °C  
SPEED: 5 M/MIN


**T600**  
Extreme



Hot Air Welding  
HEAT: 500 °C  
SPEED: 6 M/MIN

Hot Wedge Welding  
HEAT: 430 °C  
SPEED: 5 M/MIN

**112**  
Extreme



HEAT: 730 °C  
SPEED: 14 M/MIN

\*\*\*All published weld settings are estimate ranges. The settings of your machine may vary.  
The testing of all seams and all fabrics is the exclusive responsibility of the operator.

VANGUARD